



Established 1946

St. Lucie, Inc. East Coast, Inc. Treasure Coast, Inc.
Lic #'s 23863100012003-23863100032003-74160200012006-EY12000203
434 N. Seventh Street Fort Pierce, FL 34950



772-461-6845



772-468-0204



fes1946@bellsouth.net

www.free equipmentservices.com

FIRE DAMPER SERVICE

NFPA 90A

Standard for the

Installation of Air-Conditioning and Ventilating Systems

2002 Edition

B.2 Fire Dampers, Smoke Dampers, and Ceiling Dampers.

B.2.1 Each damper should be examined every 2 years to ensure that it is not rusted or blocked, giving attention to hinges and other moving parts. It is recommended that dampers operate with normal system airflow to ensure that they close and are not held open by the airstream. Care should be exercised to ensure that such tests are performed safely and do not cause system damage.

5.4.7 Maintenance. At least every 4 years, the following maintenance shall be performed:

- (1) Fusible links (where applicable) shall be removed.*
- (2) All dampers shall be operated to verify that they close fully.*
- (3) The latch, if provided, shall be checked.*
- (4) Moving parts shall be lubricated as necessary.*

CALL FOR A FREE QUOTE !

CALL 772.461.6845

Fire Extinguishers

Fire Sprinklers

Fire Alarms